From:	Angela Atkinson
То:	<u>Commissioners</u>
Cc:	Ralph Rosado; Sandra Siefken; Carla Gomez; Marlon Lobban
Subject:	Public Works Budget Amendment
Date:	Wednesday, June 28, 2023 1:28:53 PM
Attachments:	06.28.23 Budget Amendment - Public Works Sewer Department.pdf

Good afternoon Mayor, Vice Mayor, and Commissioners,

Attached you will find a budget amendment request from the Director of Public Works. The Public Works Sewer Department is transferring \$6,802.09 from Repairs & Maintenance Sewer Lines and \$9,000 from Repairs & Maintenance Equipment for a total of \$15,802.09, to Repair & Maintenance Vehicles for the Emergency Repair of the Sewer Trailer. Please see attached for the Budget amendment and Memos for more details.

This amendment is less than 5% of the total budget of each department per the Village Ordinance therefore is being distributed to the Commission and will be posted on the Village website for transparency. If you have any questions, please let me know.

Respectfully,

Angela



Budget Amendment Form

Department	Sewer Department	Date	6/21/2023
Fund(s) to be c	hanged: Sewer	I	
GL Account	GL Line Item	Transfer to:	Transfer from:

GL Account	GL Line Item	Trai	nsfer to:	Tra	nsfer from:
430-35-535-4608	Repair & Maintenance Sewer Lines	\$	-	\$	6,802.09
430-35-535-4601	Repair & Maintenance Vehicles	\$	15,802.09	\$	-
430-35-535-4602	Repair & Maintenance Equipment			\$	9,000.00
TOTAL (Columns must be equal)			15,802.09	\$	15,802.09

Description: The Sewer trailer had to be fully rebuilt/repaired and the invoice for the work totalled \$15,802.09. The fund GL#430-35-535-4601 for Repair & Maintenance of Vehicles does not have the funds to pay this invoice. We are requesting a transfer from GL#430-35-535-4608 Repair & Maintenance of Sewer Lines (\$6,802.09) and GL#430-35-535-4601 Repair & Mainenance of Equipment (\$9,000.00) to GL#430-35-535-4601 to cover this equipment/ trailer renair

N		<u> </u>
Department Director:	Date:	6/21/23
Chief Financial Officer:	_ Date:	6/28/2023
Village Manager:	_ Date:	<u>_6/28/2023</u>



North Bay Village

1666 Kennedy Causeway, Suite 300 North Bay Village, FL 33141 Tel: (305) 756-7171 Fax: (305) 756-7722 Website: www.northbayvillage-fl.gov

DATE: June 21, 2023

FROM: Marlon Lobban, Director of Public Works

SUBJECT: Emergency Repairs

City of Miami Beach Garage

Invoice 844173

The Sewer Trailer had to be totally rebuilt as the hydraulic portion broke and several other items were in need of repair.

Approved By:

Ralph Rosado, PhD, AICP Village Manager <u>06/21/2023</u> Date

Description Billing Services and P	Original Bill	Adjustments	Penalty and let	California and a state	
Billing Services and Repairs for North Bay Village PW Vehicles from May 1,2023 through May	\$17,946.27	\$0.00	Penalty and Interest \$0.00	Paid	Amount Due \$17,946.27
31, 2023					
Interest and Penalty charges may be assessed if and Please put Invoice Number or Make Checks Payable to: City of	ount due is not p 1 your check. Miami Beach, FL	baid by the due date	e. Invoice Total:	\$1	7,946.27

APPROVED By Marlon Lobban at 2:09 pm, Jun 21, 2023

MIAMIBEACH 1700 CONVENTION CENTER DRIVE MIAMI BEACH, FL 33139 (305) 673-7590

INVOICE #44183

DATE	06/20/2023
ACCOUNT	1619
AMT DUE	\$17,946.27
DUE DATE	07/20/2023

NORTH BAY VILLAGE POLICE DEPARTMENT (PUBLIC WORKS) 1666 John F Kennedy Cswy Suite 300 North Bay Village, FL 33141 USA

INVOICE CITY OF MIAMI BEACH 1700 CONVENTION CENTER DRIVE MIAMI BEACH, FL 33139 PHONE: 305-673-7641

Date 6/12/2023

ORIGINATING DEPARTMENT:

Fleet Management

Customer#: 1619

North Bay Village Police Dept. (PW) ATT: Det. Manuel Casais, Fleet Manager 1666 John Kennedy Cswy, Ste 300 North Bay Village, FL 33141

DESCRIPTION

AMOUNT

Billing Services and Repairs for North Bay Village PW Vehicles from May 1,2023 through May 31, 2023.

Summary and Details Attached:

Parts	Labor	Sublet	Credit	TOTAL	
\$13,213.64	\$2,417.91	\$2,314.72	\$0.00	\$17,946.27	
		<u>APPROVE</u> DI	<u>D:</u> EPARTMENT	HEAD:	Callos Baviz
		CH	IEF ACCOU	NTANT:	
CREDIT DISTRIBU	JTION				
ACCOUNT			AMC	UNT	
510-0000-369960-	00-307-332-00-00-00	D	\$17,	946.27	
			APPRO	OVED	

F:\MECH\\$ALL\NORTH BAY VILLAGE INVOICES\NBV-PW\FY2023 INVOICES\NBV BILLING INVOICE PW MAY 2023.DOC

.12	EQ#	WO #	PARTS	LABOR	SUBLET	MISC/CREDITS	WO AMT.
Frailer	1804PW	212598	\$11,486.20	\$2,001.17	\$2,314.72	\$0.00	\$15,802.09
entrack		214429	\$1,727.44	\$416.74	\$0.00	\$0.00	\$2,144.18
Var	TOTAL:		\$13,213.64	\$2,417.91	\$2,314.72	\$0.00	\$17,946.27

NBV WO PW MAY 2023

ruch 602 - litilities # 430.30.533.4601

\$2,144.18

Such 1804 - Server B.A. transfer 7 funds from: 430.35.535. 4608 + 4602 To: 430.35.535.4601 \$15,802.09

Operator: RP

6/13/2023 10:20:02 A

MID	Date		REPAIRS PERFORMED	
243	1	Labor Hrs OT SH RTY	RTY Description	10192320
243	01/24/2023	0.36861 N N PMA BS	PM Service PMA Service 11A	Labor Cost
243	01/24/2023	0.38972 N N 2034LN51		35.66
243	01/24/2023	1.08511 N N 2034WTZ1	Light Exterior Replace	37.71
243	01/24/2023		Repair Repair	105.08
		0.33056 N N 2034WTZ1	90BN General Repair Light System Wiring Light Wiring Repair	31.98
243	01/24/2023	1.74639 N N 2450H5M10	OOBN General Repair SprayerPressure Hose Replace	168.96
43	01/23/2023	0.69722 N N 24500000	01BN General Repair SprayerPressure System Diagnosis	67.46

		1	SUBLET REPAIRS		
Vendor	Date Back	RTY	RTY Description		
PIPE HUNTE	05/25/2023	05/25/2023 2065F55010BN General Repair HydraulicSystem		l Eluid Hydra	lic Fill Clubb
Name and a subscription of a constant	Parts: 0.00	Labor: 0.00	Other: 0.00	Tax: 0.00	Sublet Cost: 203.50
PIPE HUNTE	05/25/2023	2065F55010BN	General Repair HydraulicSystem	The second se	
and product and the second	Parts: 0.00	Labor: 0.00	Other: 0.00	Tax: 0.00	Sublet Cost: 2024.00
913547	01/24/2023	2065PS7100BN	General Repair HydraulicSystem	the second se	
	Parts: 0.00	Labor: 0.00	Other: 0.00	Tax: 0.00	Sublet Cost: 87.22

Strm	Part Number	Part Description	RTY	RTY Description	QTY	11-44 C	
F	15₩40	LUBRICANT OIL 15W40 CJ4 TIER	PMA BS	PM Service PMA Service 11A	9	Unit Cost 1 3.00	27.01
1	7W2326	FILTER OIL ENGINE 11/CAT450E EQ#4788	PMA BS	PM Service PMA Service 11A	1	14.52	14.52
1	7551527	CONNECTOR, TRAILER 7 POLE	2034CK3100BN	General Repair Light System Connector Trail Replace	1	14.57	14.57
F	4-TIRE FEE	TIRE FEE	2017TM3100BN	General Repair Tire / Tube Tire Light Replace	4	1.21	4.85
1	131745944	TIRE ST235/85R16 LR-E ENDURANCE BSW TL	2155TU0100BN	General Repair Tire / Wheel Tube Tire Inner Replace	4	170.75	682.99
	3001-0269	GAUGE PRESSURE 6000PSI 18/PIPE HUNTER	2450MH0100BN	General Repair SprayerPressure Misc Parts Replace	1	50.16	50.16
ι	90290	TIRE VALVE STEM	2017V1A100BN	General Repair Tire / Tube Valve Tire Replace	1	2.78	2.78
L	83532	TAPE TEFLON 1/2"X520"PTFE THICKER TAPE	2053T90000BN	General Repair Expendable Tape Part Issue	1	5.84	5.84
	4379200X	PUMP WATER ASSY DUAL SHAFT 1804PW	2042PS4100BN	General Repair Cooling Engine PumpEngineWater Replace	1	9965.00	9965.00
	3153381	INJECTOR FUEL DIESEL #1804PW	2044J63100BN	General Repair Fuel System Injector Fuel D Replace	1	208.80	208.80
	3012-0057	ACTUATOE 2"MINI STROKE #1804PW	2044J63100BN	General Repair Fuel System Injector Fuel D Replace	1	509.68	509.68

			MISCELLANEOUS COS	12	
Code	Code Description	RTY	RTY Description		Misc. Cost
			1	Та́ П	
			CREDITS		
Date		Description			Credit Amount
	**************************************		Work Order Total: 15	5802.09	annan an stain an stàin an stàin an stàin an stàin an stàin an stàin an t-airt ann an stàinn an stàin an stàin
Parts: 1148	6.20 Labor	: 2001.17	Sublet: 2314.72	Misc Cost: 0.00	Credit: 0.00
			NOTES		

	TICET MANAG	# 000021259	NT	1	customer copy
O Department 10 Shop:01 FL	EET MGMNT - C	SENERAL		F	weiter
Equipment		icense: XG1 Engine:		C 4.4	WO#: 0000212598
Year: 2 Make: P	narcoal 018 IPEHUNTER 00 TRAILER	GVW: Serial: Misc. Fie		12000 1T91T1620HP391	Date In: 01/17/2023 10:37
Location:					WO Status: C Last WO#:0000212598 Bill Code: N Last WO Date: 01/17/2023 Employee: 15133
Department: Class: Company: Monitor Grou Site:	238L:SEWER NBV NORTH DD: NB:NORTH B	H BAY VILLAGE CLEANER TRAII BAY VILLAGE AY VILLAGE TH BAY VILLAGE	ER I	MOUNTED	
					METERS
WO Meter	Reading	Override?		and a subscription of the	Eq Meter Actual LTD H 268 268
Н	0	A			Н 268 268
					PM SERVICE
Due		the sum larger to make		e Description M SERVICE 11A	
100 04/24/2023		A		M SERVICE 11A	
04/24/2023		۱ 	12	R	REPAIRS PERFORMED
MID	Date	Labor Hrs 01	SH	RTY	RTY Description Labor (
243	05/19/2023	1.45250 N	1	2044J63100BN	General Repair Fuel System Injector Fuel D Replace 140
243	05/19/2023	0.81611 N	1	2044J63100BN	General Repair Fuel System Injector Fuel D Replace 71
243	05/03/2023	1.33056 N	1	2044J63001BN	General Repair Fuel System Injector Fuel D 121 Diagnosis
243	05/03/2023	0.00611 N	1	2450H5M100BN	General Repair SprayerPressure Hose Replace
243	05/03/2023	1.20167 N	1	2450H5M100BN	General Repair SprayerPressure Hose Replace 11
243	05/02/2023	1.17333 N	1	2450H5M100BN	General Repair SprayerPressure Hose Replace 11
243	04/07/2023	2.02944 N	N	2450MH0100BN	General Repair SprayerPressure Misc Parts Replace 19
243	04/07/2023	0.22028 N	Ň	2450MH0100BN	General Repair SprayerPressure Misc Parts Replace. 2
243	04/05/2023	1.63222 N	N	2450MH0100BN	General Repair SprayerPressure Misc Parts Replace 15
243	04/05/2023	0.52806 N	N	2000001210BN	General Repair Vehicle/Equipt. Complete Unit 5 Move/Transport
243	02/15/2023	0.02778 N	N	2017TM1100BN	General Repair Tire / Tube Tire Heavy Replace
	02/15/2023	1.58722 N	N	2017TM1100BN	General Repair Tire / Tube Tire Heavy Replace 15
243	02/10/2023	0.77944 N	N	2450MH0100BN	General Repair SprayerPressure Misc Parts Replace 7
				7.150000000000	General Repair SprayerPressure Misc Parts Replace 7
243	02/10/2023	0.78083 N	N	2450MH0100BN	
243 243	4	0.78083 N 1.07778 N		1	General Repair SprayerPressure Misc Parts Diagnosis 10
243 243 243	02/10/2023	1.07778 N	N		General Repair SprayerPressure Misc Parts Diagnosis 10 General Repair SprayerPressure System Diagnosis 9

Page 1 of 3

y de march

1

Operator: RP

c/s

pm-a

driver side light out

check tires

machine loosing pressure

gauge broken

OPERATOR: SUPERVISOR: TEL CONTACT: CONTACT OPERATOR? VERIFY EQUIPMENT # MILES/HOURS RNI MILES AFTER RESET

-will continue working on this tomorrow...243

-diagnosed the hydraulic leak and found leaking hose...removed hose...fittings no in stock...ordered hose with new one, ok at this time...243

-diagnosed the lights on the trailer, trailer connector is not working, will need to replace and continue

diagnosis...243

-found the pump is leaking oil...ordered gaskets, front control valve is leaking, ordered valve, tires are worn and dry rotted, ordered tires...ordered new pressure gauge...243

-replaced the trailer connector and front wiring with spare wire from shop 2...rechecked operation of all

lights...found one trailer marker light not working...ordered part...243 -light come in wrong...reordered part...243

-diagnosed the pump assy and found defective packings and valves...ordered parts as needed...243 -vendor delivered pump parts and suggested front hose and leader hose replacement...verified that repairs

were wanted by the vehicle owner...started replacement of the pump valves and packings, upon complete removal of all valves, noticed the pump head is actually also pitted, requested quote for pump head or complete pump depending on pricing...ordered the hose reel hose and the leader hose...243

-started to replace the tires, when getting to the last tire, noticed that the tires were the incorrect size...size in the system is incorrect...need to reorder the tires...243 -replaced the tires with the correct size...ok at this time...243 -started replacing the pump assy...243

-completed pump replacement...243
-replaced the front water pressure gauge...243
-replaced the front control valve...243
-waiting on hose reel hose and leader hose...243
-replaced the front hose reel hose, waiting on the leader hose...243
parts in warehouse
05/12/2023 @ 15:54:43

-replaced the leader hose...243
-replaced the #1fuel injector...leaking...243
-replaced the throttle actuator...not working...243
-ready...243
charge pipe hunter in#0115739---\$1840.00 for hose and leader hose---rp
charge pipe hunter in#0115330---\$185.00 for 3/4 " valve---rp

	1 Denset T	WO# 0000214429	Operator:	JM	6/13/2023 10):20:24 AM
					CUSTOMER COPY	
0 Depart	ment:NBVPW NOR		WORKS Reput	Charles IIII		
Equipm	ent: 602PW	License: XE7740	har		THE PARTY OF THE PARTY PARTY OF THE PARTY OF	() 1900 I
Tolor: Year: Nake: Nodel:	White 2015 GMC SIERRA	Engine: 4.3L GVW: 0 Serial: 1GTN1TEH8 Misc. Field:	3FZ336454	Date I Date 0	#:0000214429 In: 05/17/2023 11:05 ut: 05/30/2023 11:47 otal Cost: 2144.18	
ocation:				WO Status: C Bill Code: N	Last W0#:000021442 Last W0 Date: 05/1 Employee: 20956	9 7/2023
Departmer Class: Company: Monitor (115A:TRU NBV NORT Group:	DRTH BAY VILLAGE PUBLIC UCK 2WD 1/2 TON TH BAY VILLAGE NORTH BAY VILLAGE PUBLI				
Site:	109 11.1	NORTH DATI FILLING	METI	ERS		
WO Meter M	Reading 14111	Override?		Ly need to the second s	TD 4111	
			PM SE	RVICE		
Due 18111 09/17/20	AAF	De Description PM SERVICE 11A PM SERVICE 11A		Due Type Type Desc 26111 B B PM SERV 05/17/2024 B B PM SERV	VICE I1B	
	an anna a suasan la sua an	t	REPAIRS I	PERFORMED		
MID	Date	Labor Hrs OT SH R		cription		Labor Cost
270	05/18/2023	3 0.31694 N 1 10		d From PM Service Charging tor Replace	g System Belt	30.60
270	05/18/2023	3 0.12833 N 1 1	0000010308N Repaire	ed From PM Service Vehicle/ Drive		
270	05/18/202	3 0.28111 N 1 1	013RZ1100BN Repaire	ed From PM Service Brakes	Rotor Brake Replace	27.2
270	05/18/202	3 0.14583 N l l	Replace	ed From PM Service Cranking e		14.1
270	05/18/202	3 0.30056 N 1 1	001B20100BN Repair	ed From PM Service Air Con	dition Belt Replace	29.0
270	05/18/202	3 0.72278 N 1 1	Replace			69.9
270	05/18/202	3 0.66694 N 1 1	Replac			64.5
270	05/17/202	3 0.48917 N 1 1	013RZ1100BN Repair	ed From PM Service Brakes	Rotor Brake Replace	e 47.3
270	05/17/202	3 0.56306 N 1 P	MB BS PM Ser	vice PMB Service 11B		54.4
270	05/17/202	0.69250 N 1 2	000001001BN Genera Diagno	l Repair Vehicle/Equipt. Sīs	Complete Unit	67.6
			SUBLET	REPAIRS		
Vendor		Date Back RTY	RTY D	escription		
			PARTS	ISSUED		
Strm P	art Number	Part Description	RTY	RTY Description	QTY Unit C	ost Total Co
	iw30	LUBRICANT OIL 5W30	PMB BS	PM Service PMB Service		.78 16.6
	PF63E	FILTER OIL CHEV.18/CHE		PM Service PMB Service		.04 7.
1 8	3-902215	WIPER BLADE 22IN 15/GM SIERRA	1C PMB BS	PM Service PMB Service	11B 2 15	
	4 6 9 9 9 6 5 7		ODT UT 2155TM2100	AN General Repair Tire /	Wheel 4 162	.72 650.

General Repair | Tire / Wheel | Tire Light | Replace

TIRE P255/70/R17 WRL FORT.HT 2155TM3100BN 112T

1

116002652

4

162.72

parts in warehouse.05/17/2023 @ 15:02:08

5/17/23 Tech 270: PMB service completed .engine oil and filter changed. wiper blades replaced, air filter replaced, topped al fluids. **Front brake pads and rotors replaced.

05/18/2023 @ 08:22:33 Tech 270: Rear Pads and rotors replaced. Battery replaced . 4 Tires mounted and balanced. A/c belt replaced. Alternator belt replaced.

NOTE Tech 270: unit came on tow truck , with no cranking , no start , Dead battery, after

completed all repairs , took it for test drive and everything workind normal, run and drives as should. transmission shift all gears ok, steering ok. brakes ok, all lights ck and ok , warning lights ck and ok .

Operator: JM

				PARTS IS	SUED			
Strm	Part Number	Part Descrip	tion	RTY	RTY Description	QTY	Unit Cost	Total Cost
F	4-TIRE FEE	TIRE FEE	and an and a second	2017TM3100BN	General Repair Tire / Tube Tire Light Replace	4	1.21	4.84
1	SG8472X	PADS BRAKE F	T 15/GMC SIERRA	2013C11100BN	General Repair Brakes Caliper Brake Replace	1	49.19	49.19
1	48880279	ROTORS BRAKE	FRONT 12/TAHOE	2013DJ1100BN	General Repair Brakes Disc Pad Brake Replace	2	74.40	148.80
1	SG8312X	PADS BRAKE RE	EAR 15/GMC	2013C11100BN	General Repair Brakes Caliper Brake Replace	1	49.19	49.19
1	48881032	ROTORS BRAKE	REAR 12/TAHOE	20130J1100BN	General Repair Brakes Disc Pad Brake Replace	2	74.40	148.80
1	2139809	ALTERNATOR 1	5/GMC SIERRA	2031AL0100BN	General Repair Charging System Alternator Replace	1	327.11	327.11
1	25040337SF	BELT SERPENT	INE 15/GMC	2031AL0100BN	General Repair Charging System Alternator Replace	1	39.42	39.42
1	9848	BATTERY 15/C	DRVETTE	2032800100BM	General Repair Cranking System Battery Replace	1	195.86	195.86
F	4-STATE FEE	STATE FEE BA	TTERY	2032800100BN	General Repair Cranking System Battery Replace	1	1.20	1.26
1	6PK2220	BELT SERPENTINE 16/GMC SIERRA		2042B24100BN	General Repair Cooling Engine Belt Cooling Replace	1	39.41	39.41
1	2488	FILTER AIR CO TAHOE/YUKON/		PMB BS	PM Service PMB Service 11B	1	17.34	17.34
				MISCELLANEO	US COSTS			
Code	Code D	escription	RTY	RTY Des	cription			Misc. Cost
				CREDI	TS			
		De	escription				Cr	edit Amount

Parts: 1727.44	Labor: 416.74	Sublet: 0.00	Misc Cost: 0.00	Credit: 0.00
	and the second	NOTES		

c/s

Unit wont turn on or start. User dept reported no oil on dipstick, check and advise. PM-B due. Check unit over.

OPERATOR: SUPERVISOR: TEL CONTACT: Felix PW NBV CONTACT OPERATOR? VERIFY EQUIPMENT # MILES/HOURS RNI MILES AFTER RESET

05/17/2023 @ 11:39:42 Tech 270: no crank , no start . Unit need a: **New Battery **PMB service.(011 and filter change ,air filter , wiper blades) ***4 Tires 225/70/R17 ** A/C belt **ALTERNATOR belt **Front pads and rotors **Rear Pads and rotors. Parts not in stock .. ALL Parts ordered 5/17/23 am